

# **BIRCHWOOD AIRPORT**

## **Contents:**

- A Pavement Strength Form showing project history, latest Pavement Condition Index (PCI) data, pavement strength ratings (if available) and other useful information
- A Pavement Condition Survey – PCI Sample Unit Layout Plan
- PCI maps showing as-measured and predicted pavement conditions
- Age map showing pavement age as of January 2003
- A Branch PCI Condition Report
- A Section PCI Condition Report

## **Airport Information:**

- Location: Approximately 20 miles north of Anchorage and 2 miles west off the Glenn Highway on North Birchwood Loop Road and Birchwood Spur Road.
- District: Anchorage
- Airport Manager: Bill Mowl
- District Maintenance Manager: Bill Mowl
- Pavement Surface: Asphalt Concrete
- Last Pavement Construction: Southeast Apron in 1987, the rest in 1978
- Pavement layout: Runway 1-19, seven taxiways and three aprons
- Design Aircraft: Twin Otter
- 2000 Enplanements: 315
- Airport Class: Non-Primary
- Last pavement condition survey: 2002
- Next planned pavement condition survey: 2005
- 2001 reported pavement maintenance and/or changed conditions: Crack sealing
- Recommendations: See PCI maps